


# MANUAL

V1.0

**3DMAKERPRO**

store.3dmakerpro.com



## 3DMAKERPRO FOX

**3DMAKERPRO**

f @3DMakerProCares

@official3DMakerPro

@3DMakerPro

https://store.3dmakerpro.com/

service@3dmakerpro.com

**JimuMeta**

f @JimuMeta

@JimuMeta

https://www.jimumeta.com/

service@jimumeta.com

Download latest **JMStudio** from

<https://forum.jimumeta.com/home/help/download.html>


Get latest **Manual** from

<https://forum.jimumeta.com/home/help/manual.html>




3D MAKERPRO LIMITED

# Hardware connection




Plug the longer "L" type plug of the device cable into the scanner, another two shorter ends into the PC USB port and power adapter respectively. (The power adapter must be connected to a power source. )

## Packing list



scanner body



power adapter



Manual Turntable



data transmission cable



D-Ring Mounting Screw

\* Product images are for illustrative purposes only.

### Operating System Requirement



|             |                                                           |
|-------------|-----------------------------------------------------------|
| Minimum     | Intel Core i5 8th, 16GB RAM, MX250 GPU with 2GB VRAM      |
| Recommended | Intel Core i7 8th, 16GB RAM, NVIDIA1060 GPU with 4GB VRAM |